



2022

REHABILITATION OF BOX CULVERT @ AUSTRALIA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 731mm x (W) 1636mm x (L) 1m Wall 32mm	13m	13	1	ONE PIECE BOX CULVERT	INTERFLOW PTY LTD AUSTRALIA(2022)
(H) 291mm x (W) 1676mm x (L) 1m Wall 32mm	12.5m	13	1	ONE PIECE BOX CULVERT	



REHABILITATION OF OVAL STORM PIPE @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1230mm x (W) 724mm x (L) 0.4m Wall 20mm	11.61m	29	3	FOUR PIECE EGG	BUDA SURVEYING LIMITED HONG KONG(2022)



REHABILITATION OF DN2550mm STORMWATER PIPE @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 2076mm x (L) 1.1m Wall 34mm	28.765m	28	2	TWO PIECE CIRCULAR	PIPELINE SOLUTIONS LIMITED HONG KONG (2022)



IL-029-21 REHABILITATION OF BHL CULVERT PACKAGE @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 629mm x (W) 1226mm x (L) 2m Wall 37mm	10.71m	6	1	ONE PIECE BOX CULVERT	ILINE TECHNOLOGIES UK (2022)



IL-133-20 REHABILITATION OF BOX CULVERT @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 960mm x (W) 1650mm x (L) 2m Wall 50mm	14.71m	9	1	ONE PIECE ARCH CULVERT	iLINE TECHNOLOGIES UK (2022)



REHABILITATION OF BRICK EGG SHAPED CULVERT @ DUBLIN, IRELAND

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 771mm x (W) 471mm x (L) 1.2m Wall 19mm	176.4m	147	4	ONE PIECE EGG	GMC UTILITIES IRELAND (2022)
(H) 1406mm x (W) 706mm x (L) 1.2m Wall 37mm	111.61m	93	3	ONE PIECE EGG	
(H) 777mm x (W) 448mm x (L) 1.2m Wall 16mm	240m	200	10	ONE PIECE EGG	
(H) 777mm x (W) 448mm x (L) 0.5m Wall 16mm	20m	40	2	ONE PIECE EGG	
(H) 777mm x (W) 448mm x (L) 1m Wall 16mm	53m	53	2	ONE PIECE EGG	



REHABILITATION OF DN750mm SEWER @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 600mm x (L) 0.8m Wall 12mm	44m	55	3	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	BUDA SURVEYING LIMITED HONG KONG (2022)



REHABILITATION OF PEACE RIVER PULP MILL SEWER @ ALBERTA, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1050mm x (L) 2.4m Wall 23mm	27.885m	15	2	ONE PIECE CIRCULAR	MICHELS CANADA (2022)
(ID) 1200mm x (L) 2.4m Wall 26mm	27.186m	16	1	ONE PIECE CIRCULAR	




REHABILITATION OF NL2 TUNNEL @ EDMONTON, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1900mm x (L) 2.2m Wall 44mm	1176m	535	8	TWO PIECE CIRCULAR WITH SLIPLINE JOINT	WHITSON CONTRACTING LTD CANADA (2022)



REHABILITATION OF RT11 ALDER BROOK FRANKLIN COUNTY @ MALONE, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 2845mm x (W) 2565.6mm x (L) 7.22ft Wall 38mm	231.1ft	33	3	TWO PIECE OVOID WITH FISH BAFFLES	TUSCARORA CONSTRUCTION CO., INC USA (2022)



REHABILITATION OF CIRCULAR SEWER DN900mm @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 740mm x (L) 0.7m Wall 14mm	68.6m	98	4	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	BUDA SURVEYING LIMITED HONG KONG (2022)



IL-002-20 REHABILITATION OF ARCH SEWER @ FLITWICK MILL, UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1285mm x (W) 1792mm x (L) 1.2m Wall 54mm	10m	9	1	ONE PIECE ARCH CULVERT	iLINE TECHNOLOGIES UK (2022)



REHABILITATION OF CIRCULAR PIPE @ NORTHAMPTON, UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 944mm x (L) 1.2m Wall 18mm	29.196m	26	1	ONE PIECE CIRCULAR	iLINE TECHNOLOGIES UK (2022)



IL-002-21 REHABILITATION OF VYNE CULVERT @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1402mm x (L) 2.4m Wall 24mm	11m	5	1	ONE PIECE CIRCULAR	iLINE TECHNOLOGIES UK (2022)
(H) 1391mm x (W) 2516mm x (L) 0.5m Wall 42mm	0.5m	1	1	ONE PIECE ARCH CULVERT	



IL-021-21 REHABILITATION OF EGG SEWER @ CLARKSTON ROAD, GLASGOW, UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1046mm x (W) 646mm x (L) 0.6m Wall 12mm	47.453m	89	4	ONE PIECE EGG	ILINE TECHNOLOGIES UK (2022)



REHABILITATION OF NORTH BAY CULVERT @ NORTH BAY, ONTARIO, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 842.4mm x (W) 1452mm x (L) 2.4m Wall 26mm	53.8m	23	2	ONE PIECE ARCH CULVERT	MILLER PAVING LIMITED CANADA (2022)



REHABILITATION OF ARCH CULVERT @ AMITY, NY, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1413.6mm x (W) 2277.2mm x (L) 7.22ft Wall 31mm	335ft	47	3	ONE PIECE ARCH CULVERT	THE L.C. WHITFORD CO INC USA (2022)



IL-009-22 REHABILITATION OF DUNHOPE SIKE CULVERT @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1406mm x (W) 2016mm x (L) 1.2m Wall 42mm	6.50m	6	1	ONE PIECE ARCH CULVERT	iLINE TECHNOLOGIES UK (2022)



REHABILITATION OF HWY 407 DN1800mm CULVERT @ TORONTO, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1652mm x (L) 2.4m Wall 24mm	44m	19	2	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	PIPEFLO CONTRACTING CORP CANADA (2022)



REHABILITATION OF 1900mm CSP CULVERT @ TORONTO, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1748mm x (L) 0.5m Wall 26mm	5.5m	11	1	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	PIPEFLO CONTRACTING CORP CANADA (2022)




REHABILITATION OF ARCH CULVERT @ TYNGSBOROUGH, MA, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 645.8mm x (W) 1179.2 x (L) 6.56ft Wall 20mm	60ft	10	1	ONE PIECE ARCH WITH SLIPLINE JOINT	TIM ZANELLI EXCAVATING LLC USA (2022)



REHABILITATION OF 60IN SPOT REPAIR PROJECT @ CITY OF HAMILTON, ONTARIO, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1267.6mm x (L) 0.9868m Wall 52mm	105m	108	5	ONE PIECE CIRCULAR	LIQUIFORCE SERVICE (ONTARIO) INC CANADA (2022)



IL-064-22 REHABILITATION OF BOWHOUSE CULVERT@ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1256mm x (L) 1.2m Wall 22mm	47m	40	2	ONE PIECE CIRCULAR	iLINE TECHNOLOGIES UK (2022)



HONG KONG - PRESSURE TEST DEMO

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 850mm x (L) 0.5m Wall 25mm	12.441m	30	2	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	PIPELINE SOLUTIONS LIMITED HONG KONG (2022)



REHABILITATION OF CULVERT SECTION 6 @ BUFFALO, NY, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 2389mm x (W) 1780mm x (L) 2.2m Wall 52mm	26m	12	1	ONE PIECE BOX CULVERT WITH SLIPLINE JOINT	RANKIN CONSTRUCTION INC USA (2022)



REHABILITATION OF EBMUD CIRCULAR PIPES @ OAKLAND, CA, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1371.6mm x (L) 2.44m Wall 30mm	1926.88ft	238	5	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	MLADEN BUNTICH CONSTRUCTION CO., INC USA (2022)
(ID) 1275.3mm x (L) 2.44m Wall 25.8mm	1988.48ft	379	5	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	



REHABILITATION OF DN1800mm SEWER @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1600mm x (L) 1m Wall 37mm	130.041m	134	4	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	BUDA SURVEYING LIMITED HONG KONG(2022)



REHABILITATION OF VIVAQUA VORST VAN VOXEM @ BELGIUM

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 385mm x (W) 557mm x (L) 2m Wall 13mm	305m	153	4	ONE PIECE INVERT	STEINZUEG-KERAMO BELGIUM (2022)





REHABILITATION OF ST. CATHERINE COLLECTOR PH 2 @ CITY OF MONTREAL, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1412mm x (W) 1132mm x (L) 2.4m Wall 27mm	165.77m	55	1	ONE PIECE EGG WITH SLIPLINE JOINT	NOVINFRA INC CANADA (2022)
(H) 1416mm x (W) 1136mm x (L) 2.4m Wall 25mm	168.2m	74	2	ONE PIECE EGG WITH SLIPLINE JOINT	



IL-245-19 REHABILITATION OF CIRCULAR SEWER @ SKIPOOL, UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1814.94-1451.03mm x (L) 1.67m Wall 25mm	1.67m	1	1	TWO PIECE CIRCULAR	iLINE TECHNOLOGIES UK (2022)
(ID) 1543.61-1450.01mm x (L) 0.93m Wall 25mm	0.93m	1	1	TWO PIECE CIRCULAR	



REHABILITATION OF CULVERT 92 ERIE CANAL @ ORLEANS COUNTY, NY, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION /YEAR
(H) 832.2mm x (W) 2026mm x (L) 2.44m Wall 55mm	93ft	12	1	ONE PIECE ARCH CULVERT WITH SLIPLINE JOINT	HOHL INDUSTRIAL SERVICES INC USA (2022)



REHABILITATION OF DISTRICT 21 INTERCEPTOR SEWER @ CITY OF LOS ANGELES, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 990.6mm x (L) 2.44m Wall 20mm	702ft	88	3	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	LUCAS BUILDERS INC USA (2022)
(ID) 1219.2mm x (L) 2.44m Wall 25mm	699ft	83	3	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	



REHABILITATION OF MP 110 TO MP 116 ARCH PIPE @ ABERDEEN, NJ, USA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 736.6mm x (W) 1066.8mm x (L) 2.44m Wall 17mm	664ft	83	3	ONE PIECE ELLIPSE WITH SLIPLINE JOINT	UNION PAVING & CONSTRUCTION CO., INC USA (2022)



REHABILITATION OF VALVE TOWER LLYN FAN FACH DAM @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 2706mm x (L) 2m Wall 72mm	11.334m	6	1	TWO PIECE EGG SEWER	iLINE TECHNOLOGIES UK (2022)



REHABILITATION OF EGG SEWER @ CITY OF WINNIPEG, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 2468mm x (W) 1618mm x (L) 2.2m Wall 26mm	33m	23	1	TWO PIECE EGG	NELSON RIVER CONSTRUCTION INC CANADA (2022)
(H) 2376mm x (W) 1486mm x (L) 2.2m Wall 27mm	117.621m	46	3	TWO PIECE EGG	
(H) 2026mm x (W) 1436mm x (L) 2.4m Wall 22mm	106m	48	1	ONE PIECE EGG	
(H) 1790mm x (W) 1342mm x (L) 2.4m Wall 20mm	68m	28	1	ONE PIECE EGG WITH SLIPLINE JOINT	



REHABILITATION OF 5F 7< '7I @ 9FH'4 'I ?

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1400mm x (W) 1650 (L) 0.5m Wall 20mm	15.50m	31	2	ONE PIECE ARCH CULVERT	iLINE TECHNOLOGIES UK (2022)



DC-2020-8 REHABILITATION OF CIRCULAR PIPE SMITHFIELD ROAD @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1385mm x (L) 1m Wall 24mm	114.071m	118	2	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	HING & CHEONG COMPANY LIMITED HONG KONG (2022)



REHABILITATION OF DN1200 PIPE @ HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1600mm x (L) 1m Wall 22mm	85.5m	85	3	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	PMPS LINER TECHNOLOGY (HONG KONG) LIMITED HONG KONG (2022)



REHABILITATION OF BRICK STORM DRAIN @ CITY OF VICTORIA, CANADA

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 700mm x (W) 1562mm x (L) 2.4m Wall 25mm	49.3m	29	2	ONE PIECE ARCH WITH SLIPLINE JOINT	PW TRENCHLESS USA (2022)
(H) 1300mm x (W) 817mm x (L) 2.4m Wall 14mm	90.6m	44	2	ONE PIECE EGG WITH SLIPLINE JOINT	
(H) 962mm x (W) 1712mm x (L) 2.4m Wall 29mm	128.867m	72	5	ONE PIECE EGG WITH SLIPLINE JOINT	



REHABILITATION OF BRICK EGG SHAPED CULVERT @ DUBLIN, IRELAND

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 777mm x (W) 448mm x (L) 0.4m Wall 16mm	27.21m	68	2	ONE PIECE EGG	GMC UTILITIES GROUP IRELAND (2022)
(H) 781mm x (W) 452mm x (L) 1.2m Wall 14mm	410.4m	342	5	ONE PIECE EGG	
(H) 779mm x (W) 450mm x (L) 1.2m Wall 15mm	230.4m	192	4	ONE PIECE EGG	



REHABILITATION OF BRICK EGG SHAPED CULVERT @ DUBLIN, IRELAND

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 769mm x (W) 469mm x (L) 1.2m Wall 20mm	204.4m	182	4	ONE PIECE EGG	GMC UTILITIES GROUP IRELAND (2022)
(H) 775mm x (W) 475mm x (L) 1.2m Wall 17mm	56.4m	47	6	ONE PIECE EGG	
(H) 775mm x (W) 475mm x (L) 1.2m Wall 17mm	156m	130	5	ONE PIECE EGG	



DC-2019-04 REHABILITATION OF DN1800mm CIRCULAR SEWER @ KWONG LEE RD, HONG KONG

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(ID) 1570mm x (L) 1m Wall 33mm	100.22m	105	4	ONE PIECE CIRCULAR WITH SLIPLINE JOINT	PIPELINE SOLUTIONS LIMITED HONG KONG (2022)



REHABILITATION OF ARCH CULVERT @ UK

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR LOCATION / YEAR
(H) 1252mm x (W) 1755mm x (L) 1.2m Wall 39mm	14m	12	1	ONE PIECE ARCH CULVERT	iLINE TECHNOLOGIES UK (2022)

